



**NATURAL AND CAST STONE**

**REPRESENTATIVE SURFACES**

- |               |         |
|---------------|---------|
| Curtain Walls | Steps   |
| Floors        | Walls   |
| Foundations   | Lintels |
| Spandrels     | Sills   |

**SURFACE PREPARATION**

WARNING! If you scrape, sand or remove old paint from any surface, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Carefully clean up with a wet mop or HEPA vacuum. Before you start, find out how to protect yourself and your family by contacting the U.S. EPA/Lead Information Hotline at 1-800-424-LEAD (5323) or log on to [www.epa.gov/lead](http://www.epa.gov/lead).

1. Remove loose particles and dirt (SSPC-SP1).
2. If oil and grease are present, solvent clean (SSPC-SP1).
3. Surface must be dry.

**PRIMERS**

No special primers needed. All coatings are self-priming over stone.



NATURAL & CAST STONE

PRODUCT RECOMMENDATIONS — NATURAL & CAST STONE

EXPOSURE CONDITIONS	PRIMER	TOPCOAT
<b>Indoor Exposure</b> to dampness and mild industrial fumes	NONE	LACRYLIC® CLEAR FINISH 7110
<b>Exterior Exposure</b> to weathering salt spray, acid and alkali liquids, and powder.s	NONE	LACRYLIC CLEAR FINISH 7110
<b>Water and Stain</b> Repellent Treatment	NONE	LACRYLIC CLEAR FINISH 7110